



SUBJECT

Calibrating the RS800 Scanner

EFFECTIVE DATE

June 2, 2003

S.O.P. NUMBER

CAL0001

DATE REVISED

June 2, 2003

PAGE

1

OF

1

## Standard Operating Procedure

1. If ColorLinx is not running, Start the application by double-clicking on the ColorLinx Icon located on the desktop.
2. Press the Calibrate button which is located on the Toolbar.
3. Enter the values from your Calibration card into the corresponding spaces in the ColorLinx software.
4. Position the aperture of the RS800 on the White block of the calibration card. Press and hold the Green button on the scanner to Calibrate to Paper White.
5. Take a spot reading on each of the KCMY patches by positioning the unit on the appropriate patch and then pressing the Green scanner button once.
6. Press the OK button on the Calibrate window.
7. Position the scanner on the White Patch that is located on the Black Calibration Plaque.
8. Press the OK button on the ColorLinx message box.
9. After the scanner beeps twice the calibration is complete\*\*. You can now remove the scanner from the Calibration Plaque and use it to take spot readings or perform scans.

\*\*Note: do not remove the scanner from the Black Calibration Plaque until you hear the two beeps.