



Standard Operating Procedure

SUBJECT

CPC 1.04 Perfecting Jobs

EFFECTIVE DATE

April 24, 2008

S.O.P. NUMBER

PERF001

DATE REVISED

April 24, 2008

PAGE

1

OF

1

This SOP outlines the operation of the Heidelberg CPTronic 1.04 Console when using ColorLinx on Perfecting Jobs.

Using ColorLinx, send Perfecting Preset Data to the On-Line Job Card

Load the Job information from the Job Card into Console Memory and then position the Data to the Keys (see *HEI-CPC104.pdf* for details)

The console will now act like two separate presses, one for the units before the perfector, the other for the units after the perfector

To switch between the 2 configurations, press the Switchover button on the console:

